



Worldwide ground supportsm



SPAIN | Madrid | Torrejon | Barajas

LETO/TOJ

N40° 29' 48.29" / W003° 26' 45.14"
23/05

Torrejon International Airport

2026 ft. 002° W Multi R +1 (+2 DST) JET
12,001 ft. x 217 ft. HIRL VORTAC VOR/DME AOE PPR SLOTS

Company name: Universal Aviation Spain S.A.
Main office: Madrid, Spain
ICAO: LETO
Locations served: All of Spain
Additional offices: Girona / LEGE
Radio frequency: 130.65 MHz
SITA: MADTJUV
Manager: Gonzalo Barona
Phone: +34 9 1 393 6890
Mobile: +34 620 909 765
Fax: +34 9 1 393 6891
E-mail: spain@universalaviation.aero
Web: universalaviation.aero

With Universal Aviation in Madrid, you...

Go Confident

- Instantly recognizable staff with Universal Aviation uniforms (in an easily accessible office)
- Industry-leading training and audit system
- Staff trained in security protocol
- 24/7 staff availability


Go Convenient

- Located adjacent to the business aviation ramp, featuring the only terrace
- Customs and immigration clearance on site
- Direct ramp access to aircraft via Universal Aviation vehicles – the only FBO with crew transportation
- VIP lounges and meeting rooms for crew and passengers

Go Competitive

- Competitive handling rates billed directly by this Universal Aviation location or through your Universal[®] account
- Attractive fixed payment terms through UVair[®]

Torrejon International Airport



- A** Parking areas
- P** Passenger meeting areas
- See next page for driving directions.

Ground support capabilities

- Office hours: 24 hours
- Located adjacent to the business aviation ramp
- Customs and immigration clearance in office building
- Slot arrangements
- UVair[®] contract fuel available
- Catering coordination
- Computerized flight planning and filing
- Computerized worldwide weather briefings
- Direct ramp access to aircraft via Universal Aviation vehicles
- Rental cars, limousines, and taxi services
- Discount crew accommodation arrangements
- VIP meeting and rest lounges
- Crew lounge

Flight Support

- **RVSM:** Implemented
- **ACAS/TCAS II:** Required for turbine aircraft with MTOW exceeding 15,000kg or more than 30 passenger seats
- **ICAO Annex 16, Chapter II:** Not Allowed
- **RNP 5 Airspace:** Yes
- **8.33 MHz Channel Spacing:** Required
- **Airport Fire Protection Category:** 4 Civil; 9 Military
- **ICAO flight plans remain in system for 15 minutes after ETD**
- Spain is under Eurocontrol Airspace. Universal has a slot coordination office in London (EGSS).



SPAIN | Madrid | Torrejon | Barajas

LETO/TOJ

N40° 29' 48.29" / W003° 26' 45.14"
23/05 12,001 ft. x 217 ft.

Torrejon International Airport

2026 ft. 002° W Multi R +1 (+2 DST)
HIRL VORTAC VOR/DME AOE PPR SLOTS

City view



 **Driving directions**

Directions to airport

From the A-2 highway (Madrid-Barcelona), take exit 22 in the direction of Base Aerea de Torrejon. 100m before the Military gate, turn left (Aeropuerto Civil). Pass through the Security Guard checkpoint and continue forward until you reach the Universal Aviation office (close to the aircraft ramp), about 1500m.

Facility address

Universal Aviation Spain S.A.
Base Aerea de Torrejon
Aeropuerto Civil
28850 Torrejon de Ardoz
Madrid, Spain

Manager: Gonzalo Barona

Phone: +34 9 1 393 6890

Mobile: +34 620 909 765

Fax: +34 9 1 393 6891

E-mail: spain@universalaviation.aero

Web: universalaviation.aero

Airport view

